

MEM20105- AA50 Certificate II in Engineering (Heavy Fabrication Pre-Apprenticeship)

Dress requirements / PPE

- Enclosed steel capped safety boots - Heavy leather uppers and heavy-duty soles
- Long heavy cotton drill trousers and long sleeve cotton drill shirt
- Safety glasses MUST be clear and meet Australian Safety Standards - No sunglasses are permitted in the workshop
- Hearing protection provided, must be worn in designated areas, as per safe operating procedures.
- Work gloves
- Welding gloves
- Disposable earplugs, gloves and dust masks will be supplied, where required.
- Long hair must be tied-up or contained

Stationery requirements

- 1 x A4 2-ring lever arch file
- A4 Lined notebook
- Black pens, lead pencils 2H or 4H, ruler
- Scientific Calculator (Mobile phone not allowed)

Textbooks

This will be discussed on your first day.

Texts can be ordered from Albany Learning Resource Centre Bookshop T | 6371 3860 E | Bookshop.GS@srtafe.wa.edu.au

Work Placement requirements

Students will be required to:

- Complete a minimum of 150 hours of work placement with an appropriate workplace.
- Arrange placement with employer, complete and submit all required forms to work placement administration BEFORE commencing placement.
- Complete logbook everyday with corresponding Daily Work Summary pages to timesheet shifts claimed.
- Bring logbook to all TAFE days for work placement administration, to collect and monitor hours throughout the placement
- Submit fully completed logbook to work placement administration